

Last Minute Notes (known issues): Software Image on **X2 extreme** panel series

Released Version	Date	Description
V1.1 B166	May 2018	Supported model types: New: X2 extreme 7, X2 extreme 7 SL HP, X2 extreme 12 SL HP, X2 extreme 15 SL HP. X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP NOTE! Update of Image requires update of related EBOOT Build 166 as well. Update EBOOT via "Make Recovery SD Card", see "Beijer Panel Image" manual (MA205x) for information.
v1.0 B118	November 2017	Initial release of the X2 extreme Sealed panel types. Supported model types: New: X2 extreme 7, X2 extreme 7 SL HP, X2 extreme 12 SL HP, X2 extreme 15 SL HP. X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP
v1.0 B117	October 2017	Initial release of the X2 extreme panel platform. Supported model types: X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP

Known issues	ID (internal)	Description and comments
No support of On screen keyboard for the iX Web browser feature.	#20128	Limitation in the Windows Embedded Operating system.
Backlight issue when two USB memory cards are mounted.	#20421	Recommended to only use one USB memory card. The usage of two USB memory cards could result in black screen (backlight not set) when rebooting the panel.
No support of mp3-format.	#21639	Audio out is not supported on X2 panels. Dialogue is presented, but the built in Media player feature will not play the mp3-format.
PDF-viewer limitations.	#21641	Bookmark limitations when using the built in PDF-viewer feature. Vertical scroll picker height too small to maneuver.
DHCP (Dynamic IP setting)	#22540	It is always recommended to use the Static IP settings. LAN A = default Static IP LAN B = default DHCP IP (Dynamic) The configuration for the LAN-ports can be configured via the Service menu, see Image manual MA205x for details.
SD-card writing	#22655	Repeat the write procedure if the SD-card write error appears.

Last Minute Notes (known issues):

Software Image on **X2 extreme** panel series

Known issues	ID (internal)	Description and comments
Delay in touch functionality when mounting SD-card.	#22852	If a SD memory card is mounted during panel is running the touch functionality could be delayed up to 5 seconds before initiating. Recommended to install SD card when unit is disconnected from power.
Limited graphical performance with display rotation.	#22949	Graphical performance on Display affected if panel screen configured is rotated 180 Degree.
Sporadic COM errors.	#22861	During heavy load the panel can show intermittent com errors.
Color scheme differs from older HMI products.	#23810	Color scheme for windows controls differs compared to older HMI products, used a different version of Microsoft Embedded operating system.
Limitation in Media player object.	#28575	Supports only presentation of one instance of Media player object at the same time.
Compatibility using C# script compare to older panel series	#30918	Space and Mark parity in C# scripting, to handle Serial Port communication, is not supported by the hardware on X2 panels.
The PDF viewer doesn't always present the document fully.	#31491	There are limitations to display of table of contents, headings, table text and scroll bar in the operating system. This depends on used font license. See restriction from Microsoft: https://support.office.com/en-us/article/About-font-license-restrictions-6be9f366-e722-4751-90a8-165e9c37e985?ui=en-US&rs=en-US&ad=US&fromAR=1
No information about IP conflict.	#33015	No warning will show up if an IP address is already used in the network.
No support of SD-card 64 GB and larger size.	#35054	SD-cards larger than 32GB are usually formatted as exFAT. To get full support, the SD cards must be formatted as FAT32. (max 32GB recommend)